

United States Patent and Trademark Office

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
10/043,925	10/23/2001	Manfred Boldy	DE920000041US1	9258
7590 05/24/2004		EXAMINER		
Andrew Calderon			OMGBA, ESSAMA	
McGUIRE WOODS LLP 1750 Tysons Blvd,,, Suite 1800			ART UNIT	PAPER NUMBER
McLean, VA 22102			3726	
		DATE MAILED: 05/24/2004		

Please find below and/or attached an Office communication concerning this application or proceeding.

U.S. Patent and Trademark Office PTOL-326 (Rev. 1-04) Application/Control Number: 10/043,925

Art Unit: 3726

DETAILED ACTION

Claim Rejections - 35 USC § 103

- 1. The following is a quotation of 35 U.S.C. 103(a) which forms the basis for all obviousness rejections set forth in this Office action:
 - (a) A patent may not be obtained though the invention is not identically disclosed or described as set forth in section 102 of this title, if the differences between the subject matter sought to be patented and the prior art are such that the subject matter as a whole would have been obvious at the time the invention was made to a person having ordinary skill in the art to which said subject matter pertains. Patentability shall not be negatived by the manner in which the invention was made.
- 2. Claims 1 and 3-17 are rejected under 35 U.S.C. 103(a) as being unpatentable over Applicant's Admitted Prior Art (AAPA) in view of Grois et al. (US Patent 6,434,315).

With regards to claims 1 and 13, Applicant, at pages 1 and 2 of the specification to be known as AAPA, discloses a cable mounted to a connector with ends of the cable marked for identification purpose. AAPA does not disclose a strain relief clamp with a transparent portion through which a marking of interest is visible when the strain relief clamp is installed on the connector. However Grois et al. teaches a strain relief component 74 with a transparent portion 80 affording visual inspection of the cable within the connector, see column 3, lines 46-66. Therefore it would have been obvious to one of ordinary skill in the art at the time the invention was made, to have provided a strain relief clamp with a transparent portion in the connector of AAPA, in light of the teachings of Grois et al., in order to afford visual inspection of the cables. Applicant should note that it is within the general knowledge of one of ordinary skill in the art to provide appropriate shape transparent portions on the strain relief clamp.

For claims 3-6, 8, 9 and 14-17, see column 3, lines 66-67, column 4, lines 1-2 and figure 1. Applicant should note that it is within the general knowledge of one of

Application/Control Number: 10/043,925

Art Unit: 3726

ordinary skill in the art to provide appropriate shape transparent portions on the strain relief clamp.

For claim 7, Applicant, at pages 1 and 2 of the specification to be known as AAPA, discloses a method for identifying a cable that has identification markings on its end section wherein cable ends are marked for identification and mounted to connectors. AAPA does not disclose a strain relief clamp with a transparent portion through which a marking of interest is visible when the strain relief clamp is installed on the connector. However Grois et al. teaches a strain relief component 74 with a transparent portion 80 affording visual inspection of the cable within the connector, see column 3, lines 46-66. Therefore it would have been obvious to one of ordinary skill in the art at the time the invention was made, to have provided a strain relief clamp with a transparent portion in the connector of AAPA, in light of the teachings of Grois et al., in order to afford visual inspection of the cables.

For claims 10-12, see column 3, lines 66-67, column 4, lines 1-2 and figure 1.

Applicant should note that it is within the general knowledge of one of ordinary skill in the art to provide appropriate shape transparent portions on the strain relief clamp.

3. Claim 2 is rejected under 35 U.S.C. 103(a) as being unpatentable over AAPA/Grois et al. as applied to claim 1 above, and further in view of Beier et al. (US Patent 6,367,897).

AAPA/Grois et al. discloses a strain relief clamp as shown above except for the strain relief clamp including an antikink protective sleeve. However it is known to provide antikink sleeves to connectors as attested by Beier et al., see column 4, lines

Art Unit: 3726

22-25 and figure 1. Therefore it would have been obvious to one of ordinary skill in the art at the time the invention was made, to have provided the strain relief clamp of AAPA/Grois et al. with an antikink protective sleeve, in light of the teachings of Beier et al., in order to prevent buckling of the cable.

Response to Arguments

4. Applicant's arguments with respect to claims 1-7 have been considered but are most in view of the new ground(s) of rejection.

Conclusion

5. The prior art made of record and not relied upon is considered pertinent to applicant's disclosure.

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Essama Omgba whose telephone number is (703) 305-2915. The examiner can normally be reached on M-F (10-7:30) First Friday off.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Peter Vo can be reached on (703) 308-1789. The fax phone number for the organization where this application or proceeding is assigned is 703-872-9306.

Application/Control Number: 10/043,925 Page 5

Art Unit: 3726

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

Duffa

eo May 20, 2004